



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
February 13, 2007

*Handwritten initials: JCB*

**Mine Name:** Henrietta 21  
**Operator Name:** James C. Petersen.

**Permit number:** S/03/029  
**Inspection Date:** June 15, 2006  
**Time:** 2:00 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** None  
**Mine Status:** Inactive.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**  
Routine inspection while in the area.

**Inspection Summary:**  
1. This site did not appear to have been much change since the last inspection, other than a small amount of rock had been removed (probably last year). Permit boundary markers were still in place except one that had been knocked down (probably by snow). There was no erosion problems noted and the site was generally clean of trash. No compliance problems noted.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**  
Continue to monitor this site when in the area.

**Inspector's Signature**

LK:jb

O:\M003-BoxElder\S0030029-Henrietta21\inspections\Insp-06152006.doc